
























N704P379112D&N704P379112E


Assembly Instruction






A  93PCS	B  93PCS	C  M3.5*15mm 82PCS	D  M6*40mm 4PCS
E  M6*15mm 4PCS	F  M4*18mm 4PCS	G  16PCS	H  4PCS
I  2PCS	J  2PCS	K  2PCS	L  1PC
M  2PCS	N  2PCS	O  4PCS	P  2PCS
Q  2PCS	R  2PCS	S  2PCS	T  2PCS
U  1PC			

STEP 1




	Ax8
	Bx8

STEP 2




	Ax14
	Bx14

STEP 3




	Dx4
---	-----

STEP 4




	Cx8
	Ox2

STEP 5




	Ax6
	Bx6

STEP 6




	Ax6
	Bx6

STEP 7




	Ax4
	Bx4
	Cx4
	Ix2

STEP 8




	Ax15
	Bx13
	Gx6


STEP 9



STEP 10




STEP 11



	Ax16
	Gx10


STEP 12



	Bx16
---	------

STEP 13


X2



	Ax24
	Bx24


STEP 14

X2




	Cx12
	Fx4
	Px2

STEP 15




	Cx2
	Lx1

STEP 16




	Ex4
	Qx2
	Rx2

STEP 17




	Cx6
	Lx1

STEP 18




	Hx4
	Cx8

STEP 19




	Cx8
---	-----

STEP 20




	Cx12
	Jx2
	Nx2

STEP 21



	Cx8
	Kx2

STEP 22



	Cx2
	Sx2
	Tx2